TCDS No.: E.104 Centurion 3.0 series engines

Issue: 01 Date: 20 June 2017



# TYPE-CERTIFICATE DATA SHEET

No. E.104

## for

Technify Motors GmbH Centurion 3.0 series engines

Type Certificate Holder
Technify Motors GmbH
Platanenstr. 14
D-09356 Sankt Egidien
Germany

For Models: Centurion 3.0



Intentionally left blank

## **TABLE OF CONTENTS**

I. General	4
1. Type/ Model	4
2. Type Certificate Holder	4
3. Manufacturer	4
4. Date of Application	4
5. EASA Type Certification Date	4
II. Certification Basis	4
1. Reference Date for determining the applicable airworthiness requirements:	4
2. EASA Certification Basis	4
2.1. Airworthiness Standards	4
2.2. Special Conditions (SC)	5
2.3. Equivalent Safety Findings	5
2.4. Deviations	5
2.5. Environmental Protection	5
III. Technical Characteristics	5
1. Type Design Definition	5
2. Description	5
3. Equipment	5
4. Dimensions	5
5. Dry Weight	5
6. Ratings	6
7. Control System	6
8. Fluids (Fuel, Oil, Coolant, Additives)	6
9. Aircraft Accessory Drives	6
IV. Operating Limitations	6
1. Temperature Limits	6
2. Speed Limits	7
3. Pressure Limits	7
4. Operating Altitude	7
5. Time Limited Dispatch (TLD)	7
V. Operating and Service Instructions	7
VI. Notes	
SECTION: ADMINISTRATIVE	9
I. Acronyms and Abbreviations	9
II. Type Certificate Holder Record	9
III. Change Record	9

Issue: 01 Date: 20 June 2017

## I. General

# 1. Type/ Model

Centurion 3.0 / Centurion 3.0

## 2. Type Certificate Holder

Technify Motors GmbH Platanenstr. 14 D-09356 Sankt Egidien Germany

**DOA EASA.21J.010** 

#### 3. Manufacturer

**Technify Motors GmbH** 

POA DE.21G.0269

## 4. Date of Application

Centurion 3.0		
19 December 2013		

# **5. EASA Type Certification Date**

ſ	Centurion 3.0		
Ī	20 June 2017		

## **II. Certification Basis**

## 1. Reference Date for determining the applicable airworthiness requirements:

20 June 2014

#### 2. EASA Certification Basis

# 2.1. Airworthiness Standards

CS-E, Amendment 3, dated 23 December 2010



TE.CERT.00052-001 © European Aviation Safety Agency, 2017. All rights reserved. ISO9001 Certified. Page 4 of 9 Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Issue: 01 20 June 2017

#### 2.2. Special Conditions (SC)

Addition to CS-E 210 Failure Analysis, Addition to CS-E 240(d) Engine Flame Out during Flight

#### 2.3. Equivalent Safety Findings

CS-E 70, 100, 110 - Type design

CS-E 130(h) – Fireproofness of engine attachment points

CS-E 440(b)(3) Endurance Test – Schedule for Engine Incorporating a Turbocharger

#### 2.4. Deviations

None

#### 2.5. Environmental Protection

None (not required for piston engines)

## **III. Technical Characteristics**

#### 1. Type Design Definition

TDD-06-01, Issue 1 dated 10 October 2016 or later approved issue/revision

## 2. Description

The Centurion 3.0 engine is a V6-cylinder, four stroke Diesel piston engine with an displacement of 2987 cm³, equipped with common rail high pressure direct injection, turbocharger, gearbox with reduction ratio of 1: 1.66 and an Electronic Engine Control Unit (EECU).

## 3. Equipment

See Installation Manual

#### 4. Dimensions

Model	Centurion 3.0		
Overall Length	980 mm		
Overall Height	700 mm		
Width	790 mm		

#### 5. Dry Weight

Model	Centurion 3.0		
Weight	265 kg		



TCDS No.: E.104

Issue: 01 20 June 2017

#### 6. Ratings

Rating		Centurion 3.0		
		221 kW (300 HP)		
	Take-off (5 min)	at 3880 engine rpm		
Power		(2340 prop rpm)		
		202 kW (272 HP) at		
	Max. Continuous	3880 engine rpm		
		(2340 prop rpm)		

Note: The performance values specified above correspond to minimum values defined under the conditions of ICAO or ARDC standard atmosphere.

## 7. Control System

The engine is equipped with an Electronic Engine Control Unit (EECU). Software verified to level C according to RTCA Document DO-178B.

FADEC P/N 06-7610-E000202 or later approved standard

Software: D6-v1.00 or later approved standard

Software Mapping: Refer to Service Bulletin TM TAE 000-0007 for approved software P/N.

# 8. Fluids (Fuel, Oil, Coolant, Additives)

See Operation & Maintenance Manual for approved fluids (see also Note 4).

#### 9. Aircraft Accessory Drives

	Rotation	Speed (rpm)	Max. Torque	Type of Drive
Accessory Drive	CCW	3900	13 Nm	AND 20000 modified

CCW = Counter-Clock-Wise

Speed is indicated for a reference engine speed of 3880 rpm.

Accessory drive direction of rotation is as viewed facing the drive.

#### **IV. Operating Limitations**

## 1. Temperature Limits

	Temperature in °C / °F	Comments
Minimum opening up Oil Temperature	50 °C / 122 °F	
Max. Oil Temperature:	139 °C / 282 °F	
NAIi	+5 °C / 41 °F	With 32 ≤ Cetane N° < 38
Minimum Ambient Temperature for Starting	-25 °C / -13 °F	With Cetane N° ≥ 38
Minimum Fuel Temperature during operation	-25 °C / -13 °F	
Minimum opening up Cooling Fluid Temperature	60 °C / 140 °F	
Max. Cooling Fluid Temperature	105 °C / 221 °F	
Max. Gearbox Temperature	130 °C / 266 °F	
Max. Exhaust Gas Temperature	850 °C / 1562 °F	



TCDS No.: E.104 Issue: 01

20 June 2017

#### 2. Speed Limits

Maximum Engine Over-speed (Crankshaft Speed)	4220 rpm (2500 prop rpm)
Take-off speed	2000 mm /2240 mm mm)
Max. continuous speed	3880 rpm (2340 prop rpm)

## 3. Pressure Limits

Minimum Fuel Pressure (at inlet of feed pump)	200 mbar (2.9 psi) (absolute)
Maximum Fuel Pressure (at inlet of feed pump)	3 bar (43.5 psi) (absolute)
Minimum Oil Pressure at Idle Conditions	1 bar (14.5 psi)
Oil Pressure (normal operation)	2.3 6.0 bar (33.4 87 psi)
Maximum Oil Pressure	6.5 bar (94.3 psi)

## 4. Operating Altitude

Maximum altitude	7620 m (25000 ft)

# 5. Time Limited Dispatch (TLD)

The engine is not approved for Time Limited Dispatch. All engine systems and equipment must be functional prior to aircraft take-off. Any detected engine system or equipment failure must be corrected before next flight. For special instructions, see OM-06-01.

# V. Operating and Service Instructions

Manuals	Centurion 3.0	
Installation Manual	IM-06-01	
Operation Manual	OM-06-01	

Instructions for Continue	d Centurion 3.0	
Airworthiness (ICA)		
Maintenance Manual	OM-06-01	
Overhaul Manual	not issued yet	

Service Bulletins as issued.

Centurion 3.0 series engines

TCDS No.: E.104 Issue: 01

20 June 2017

#### VI. Notes

- **Note 1:** The EASA approved Airworthiness Limitations Section of the Instructions for Continued Airworthiness is published in the applicable "Operation & Maintenance Manual" document, chapter 06-OM-05-01 "Airworthiness Limitations". This ALS section is empty because no life limit is necessary for these models.
- **Note 2:** Suffixes in parentheses may be added to the engine model number to define installation specific configuration changes. The software of the electronic engine control for each application has a specific software mapping. See Service Bulletin TM TAE 000-0007 for the installation versions and software mappings. Also refer to Installation Manual for appropriate installation.
- **Note 3:** The Centurion 3.0 series engines are approved for the installation in Part 23 normal and utility category airplanes.
- Note 4: The Centurion 3.0 series engines are approved for operation with jet fuels (see Operation Manual OM-06-01). The engine has been tested for fuels up to a maximum ignition delay time of 6,78 ms resp. a minimum derived cetane number of 32 (determined according EN 15195/ASTM D6890).
- **Note 5:** The Centurion 3.0 engine, including the FADEC, is approved for use with the propeller MTV--12-D/210-56 models. This approval does not include the approval of the propellers and their control systems.
- **Note 6:** This engine design features an integrated propeller control in the FADEC. The software in the FADEC has been developed in accordance with DO-178B at level C. The approval of the engine and its FADEC does not include approval of the propeller control system.
- Note 7: The recommended Time Between Overhaul (TBO) is published in SB TMG 300-0001.
- **Note 8:** The engine control system has been tested according to DO-160G for lightning protection and magnetic interference. The demonstrated levels are declared in the Installation Manual.
- **Note 9:** The EECU must not be installed in a dedicated fire zone. The installation conditions are defined in the Installation Manual.
- **Note 10:** Installation Assumptions: See Installation Manual.
- **Note 11:** Containment has been demonstrated for max. turbocharger speed of 192500 rpm.
- **Note 12:** Sales name of the model Centurion 3.0: CD-300



TCDS No.: E.104 Centurion 3.0 series engines

Issue: 01 20 June 2017

# **SECTION: ADMINISTRATIVE**

I. Acronyms and Abbreviations

n/a

**II. Type Certificate Holder Record** 

n/a

# **III. Change Record**

ſ	Issue	Date	Changes	TC issue
ſ	Issue 01	20 June 2017	Initial Issue	Initial Issue,
				20 June 2017

-END-